

FIG.1




FIG.2




FIG.3




FIG.4




FIG.5




FIG.6




FIG.7




FIG.8A





FIG.8B




FIG.8C

FIG. 9A

FIG.9A





FIG.9B




FIG.9C

FIG.10




FIG.11A




FIG.11B

FIG.11C

FIG. 12A

FIG.12A





FIG.12B

FIG.12C

FIG. 13

FIG.13




FIG.14A





FIG.14B




FIG.14C

FIG. 15A

FIG.15A





FIG.15B




FIG.15C

FIG. 16

FIG.16




FIG.17A






FIG.17B

FIG.17C

FIG. 18A






FIG. 19




FIG.20A





FIG.20B





FIG.20C

FIG.21A

FIG.21B






FIG.23A




FIG.23B




FIG.24A




FIG.24B




FIG.25




FIG.26A




FIG.26B




FIG.27A




FIG.27B




FIG.28



100020.02510000

FIG.29A




FIG.29B





FIG.30



106020-32510600

FIG.31A




FIG.31B




FIG.32A





FIG.32B




FIG.32C

FIG.33




FIG.34A




FIG.34B




FIG.35A




FIG.35B




FIG.36




FIG.37A




FIG.37B




FIG.38A




FIG.38B




FIG.39




FIG.40A




FIG.40B




FIG.41A




FIG.41B




FIG.41C




FIG.42




FIG. 43A

FIG.43A




FIG.43B




FIG.44A




FIG.44B




FIG.44C




FIG.45




FIG. 46A

FIG.46A




FIG.46B




FIG.46C

FIG.47A




FIG.47B




FIG. 48A

FIG.48A





FIG.48B




FIG.48C

FIG.49




FIG. 49

FIG.50A




FIG.50C





FIG.50B

FIG.51




FIG. 52

FIG.52




FIG.53A




FIG.53C





FIG.53B

FIG.54




FIG.55




FIG.56




FIG.57




FIG.58




FIG.59A




FIG.59C





FIG.59B




FIG.59D

FIG. 60A

FIG.60A





FIG.60B




FIG.60C

FIG.61




FIG.62A




FIG.62C





FIG.62B




FIG.62D

FIG. 63A

FIG.63A





FIG.63B




FIG.63C

FIG.64




FIG.65A




FIG.65C






FIG.65B

FIG.65D

FIG. 66A





FIG.66B




FIG.66C

FIG. 67

FIG.67




FIG.68A




FIG.68C





FIG.68B




FIG.68D

FIG.69A





FIG.69B




FIG.69C

FIG. 70

FIG.70




FIG.71





FIG. 72



2001-01-01




FIG. 74

FIG.74




FIG.75




FIG.76A




FIG.76B




FIG.76C

